



## Operation steps of T5D057.

1. Put the " T5UID1 擦除.BIN " file in the DWIN\_SET folder and download it to the T5D057 tool with an SD card.



- 2, Use the T5D057 tool to plug it into the jack on the back of the screen and download it to the screen.

- 3, Put "T5UID1.BIN" in the DWIN\_SET folder and download it to the T5D057 tool with an SD card.



4, Use the T5D057 tool to plug it into the jack on the back of the screen and download it to the screen.

5. Finally, download the "T5L\_OS\_DGUS2\_V10.BIN" and your own project SD card from the SD card slot on the screen into the screen according to the normal method of downloading the project.